

List of Refrigeration Measures

1. Low Temp. Open Case to Reach-In
2. Medium Temp. Open Case to Reach-In
3. Low Temp. Coffin to High Efficiency Reach-In
4. Low Temp. Reach In to High Efficiency Reach-In
5. Special Doors with Low Anti-Sweat Heat
6. High Efficiency Multiplex Compressor System
7. Floating Head Pressure Controllers
8. Floating Suction Pressure Controllers
9. Efficient (oversized) Condenser – Air or Evaporative Cooled
10. Air Cooled to Evaporative Cooled Condenser
11. Evaporator Fan Controller for Walk-In Coolers/Freezers
12. Anti-Sweat Heater Controls
13. Efficient Evaporator Fan Motor (ECM or PSC) for Cases
14. Efficient Evaporator Fan Motor (ECM or PSC) for Walk-In Coolers/Freezers
15. Efficient Compressor – Low Temperature Circuits
16. Variable Frequency Drive for Compressor Motors
17. Night Covers (vertical and horizontal)
18. Strip Curtains for Walk-In Boxes
19. Insulate Bare Suction Lines
20. Door Gaskets for Main Door of Walk-In Coolers/Freezers
21. Door Gaskets on Reach-In Glass Doors
22. Auto-Closers for Main Door of Walk-In Coolers/Freezers
23. Auto-Closers for Reach-In Glass Doors
24. Vending Machine Controller
25. Beverage Merchandise Controller
26. Case Lighting (T12 to T8)
27. Case Lighting T12 Magnetic to Electronic Ballast
28. CFL in Walk-In (from Incandescent)
29. Hardwired T8 Fluorescent 4' in Walk-In Coolers/Freezers
30. Variable Frequency Drive for Evaporator Fan Motors
31. Variable Frequency Drive for Condenser Fan Motors
32. Variable Frequency Drive for HVAC Fan Motors
- Potential**
33. Floating Head Pressure by Lowering the Set Point
34. LED Case Lighting
35. 2-Stage ECM motors for Cases
36. ASH Control by Installing GE-ASH-Control Film